

SCHOOL BUILDING RESTORED WITH BELZONA

ID: 3974



PROBLEM

The stone work was weathering and the brick work was dirty. In addition there were areas suffering from rainwater ingress.

APPLICATION SITUATION

School building suffering for the effects of the weather

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets WPA-4 & 8. The Belzona 4141 was tinted with a cement tone additive to colour match the repair with the Bath Stone and to ensure a visually pleasing repair. The final stage of the application was to overcoat the surface with Belzona 5122.

BELZONA FACTS

Belzona completed the application to a high standard and the council responsible for the school was very pleased with the aesthetics of the repair application.

INDUSTRY

Buildings & Structures

LOCATION

Comprehensive School, South Wales

APPLICATION DATE

February 2012

PRODUCTS

Belzona 4141 (Magma Build)
Belzona 5122 (Clear Cladding Concentrate)

SUBSTRATE

Bath Stone & Brick Fascia

PHOTOS

1. Front of the school with damaged areas of concrete
2. Damaged areas repaired with Belzona 4141
3. Application of Belzona 5122
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

