

BELZONA ELASTOMER REPAIR TO SEVERELY DAMAGED HOSE

ID: 398



PROBLEM

Holes, cuts and tears in the rubber covers of five floating pipes.

APPLICATION SITUATION

Large diameter floating rubber pipes used in dredging.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Belzona Elastomer repairs offer a rapid solution to torn and damaged floating hoses, at a fraction of the replacement cost. Additional strength was provided in some areas by bonding Neoprene rubber sheets over damaged areas.

INDUSTRY

General Industry

LOCATION

Dredging Company in Holland

APPLICATION DATE

October 1987

PRODUCTS

Belzona 2111 (D & A Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Typical tear in rubber pipe.
2. Application of Belzona 2111.
3. Floating pipe in service with neoprene patch bonded with Belzona 2111.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

