


BELZONA SOLVES DREDGE PUMP WOES

ID: 40



PROBLEM

Large roots and stones damaged cutwater and stripped rubber coating from pump.

APPLICATION SITUATION

Dredge pump repair.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet CEP-1.

BELZONA FACTS

Application proceeded rapidly using Belzona® 2311 (SR-Elastomer) to achieve full mechanical properties in less than two hours with minimal downtime for the dredge pump operator.

INDUSTRY

Marine

LOCATION

Marine contractor, Panama City, Florida, U.S.A.

APPLICATION DATE

August 1999

PRODUCTS

Belzona 2311 (SR-Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. The damage
2. Completed repair
3. Dredge pump ready for service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

