

BELZONA REBUILDS DAMAGED DECK FLOOR

ID: 4040



PROBLEM

Severe pitting corrosion had occurred on the deck floor which needed rebuilding.

APPLICATION SITUATION

Corrosion occurring on deck floor

APPLICATION METHOD

This was carried out using a modified version of FPA-1. After surface preparation the Belzona 1121 could be applied to restore the deck to its original dimensions.

BELZONA FACTS

Belzona can return badly corroded areas back to their original dimensions and its has the capability to handle high compressive loads.

INDUSTRY

Chemical & Petrochemical

LOCATION

Egypt

APPLICATION DATE

2007

PRODUCTS

Belzona 1121 (Super XL-Metal)

SUBSTRATE

Mild Steel

PHOTOS

1. Damaged Area
2. Surface Preparation
3. Belzona 1121 application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

