

BELZONA PROVIDES INTERNAL CORROSIVE RESISTANT LINING

ID: 4041



PROBLEM

Corrosion occurring on the internal surfaces which needed to be protected.

APPLICATION SITUATION

Media filter requiring internal lining

APPLICATION METHOD

The repair was carried out in accordance with TCC-3. The two different coloured coats of Belzona 5811 were applied to avoid any pinholes or misses.

BELZONA FACTS

Belzona 5811 can be spray applied therefore larger applications can be completed quicker.

INDUSTRY

Oil & Gas

LOCATION

Egypt

APPLICATION DATE

March 2006

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Carbon Steel

PHOTOS

1. Corrosion Damage
2. 1st coat successfully applied
3. 2nd coat application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

