

BELZONA PROTECTS COOLING WATER SPOOLS

ID: 410



PROBLEM

Previous coating was badly damaged allowing severe erosion-corrosion on pipework internals.

APPLICATION SITUATION

Main cooling water intake pipework.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-2.

BELZONA FACTS

Some spools were so badly corroded that they had to be replaced or sleeved. The Belzona® 1341 coating will prevent future costly replacement becoming necessary.

INDUSTRY

Power

LOCATION

Power station - Ireland

APPLICATION DATE

2003

PRODUCTS

Belzona 1341 (Supermetalglide)

SUBSTRATE

Steel

PHOTOS

1. General view of the spools
2. Degree of original erosion clearly evident
3. Application underway
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

