

BELZONA SEALS ROOF OVER PRODUCTION AREA

ID: 4158



PROBLEM

The effect of weather and UV caused rubber seals around ductwork penetrations to degrade allowing rainwater to leak directly into the production area creating disruption in production and safety issues.

APPLICATION SITUATION

Extraction outlets on roof over production area.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1 and 6. The joints were resealed with Belzona Elastomer, before applying a fully reinforced Belzona® 3111 Flexible Membrane system.

BELZONA FACTS

Belzona system was applied in 2 days without disrupting production, giving a long term water and weather resistant solution.

INDUSTRY

General Industry

LOCATION

Manufacturer, UK

APPLICATION DATE

September 2012

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 3111 (Flexible Membrane)

SUBSTRATE

Steel

PHOTOS

1. Deteriorated joint
2. Belzona 2211 applied to seal gap
3. All joints sealed with Belzona Elastomer
4. Fully Reinforced Belzona 3111 system applied to give additional sealing and protection

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

