


# BELZONA CREATES SAFE ENTRANCE FOR WORKERS AND VISITORS

ID: 4175



## PROBLEM

New quarry tiled floor at the entrance to the factory reception was extremely slippery when wet. This identified slip hazard had to be made good by the client.

## APPLICATION SITUATION

Main entrance to the factory. All staff and visitors pass through this area on their way in and out of the factory.

## APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

## BELZONA FACTS

Belzona provided an acceptable and cost effective solution. Application was carried out late in the evening, in order not to disturb customers during his operating hours. In the morning the floor was ready. Belzona solution eliminated the trip hazard and provided durable and nice-looking non-slip system. The expensive alternative was to replace the quarry tiles.

## INDUSTRY

General Industry

## LOCATION

Building materials manufacturer, Croatia

## APPLICATION DATE

October, 2012.

## PRODUCTS

Belzona 1321 (Ceramic S-Metal)

## SUBSTRATE

Quarry tile

## PHOTOS

1. New quarry tiles that are very slippery when wet
2. Application in progress - creation of pattern
3. Application finished
4. Application finished - close up shot

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

