

BELZONA REBUILDS AND PROTECTS PUMP CASING AND IMPELLER

ID: 4192



PROBLEM

Pump casing and impeller had become damaged due to erosion-corrosion

APPLICATION SITUATION

Pump casing and impeller

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflets CEP-1 and CEP-3.

BELZONA FACTS

Belzona 1321 provides excellent abrasion resistance and will completely eradicate the threat of corrosion.

INDUSTRY

Fluid Flow

LOCATION

Port Said, Egypt

APPLICATION DATE

March 2007

PRODUCTS

Belzona 1311 (Ceramic R Metal)
Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Original Damage
2. Belzona 1311 completed application
3. Belzona 1321 application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

