




BELZONA RESTORES TUBE SHEET PROTECTION

ID: 4197



PROBLEM

Original coating on tube sheet had failed. Replacement required to prevent future corrosion.

APPLICATION SITUATION

condenser Tube Sheet

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet HEX-3.

BELZONA FACTS

The Belzona repair was carried out quickly, minimizing outage time. Belzona® 1321 has a long track record of providing corrosion protection on such equipment.

INDUSTRY

Power

LOCATION

Power station, Cairo, Egypt

APPLICATION DATE

September 2003

PRODUCTS

Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Damaged original coating
2. After surface preparation
3. First coat of Belzona 1321 applied
4. Second coat of Belzona 1321 applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

