

SOAP POWDER CAN'T WASH BELZONA AWAY!

ID: 420



PROBLEM

Corrosion from the soap powder and water mixture damages the housing and rotating elements of the mixer.

APPLICATION SITUATION

Soap Mixer

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

BELZONA FACTS

The customer is pleased with the performance of the Belzona coating and there is an on-going program to protect these mixers.

INDUSTRY

General Industry

LOCATION

Manufacturer of washing powder in Italy

APPLICATION DATE

On-going since 2002

PRODUCTS

Belzona 4311 (Magma CR1)

SUBSTRATE

Cast Steel

PHOTOS

1. The mixer as it arrives
2. The coated rotating elements
3. The mixer end covers coated
4. The mixer body coated

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA