

BELZONA REBUILDS AND PROTECTS FANS

ID: 4200



PROBLEM

Belzona was required to rebuild and protect damaged fan blades

APPLICATION SITUATION

Fan blades

APPLICATION METHOD

The application was carried out in accordance with Belzona Know How System Leaflets FBC-1 and FBC-2.

BELZONA FACTS

The Belzona solution will provide a corrosion and erosion resistant coating for long term protection.

INDUSTRY

Fluid Flow

LOCATION

Sharkeya, Egypt

APPLICATION DATE

May 2006

PRODUCTS

Belzona 1311 (Ceramic R Metal)

Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. Before application
2. Belzona 1311 application
3. Belzona 1321 application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

