

BELZONA 3211 (LAGSEAL) IN TOUGH ENVIRONMENT - 2ND TIME AROUND

ID: 423



PROBLEM

After eight years of service the previously applied Belzona® 3211 (Lagseal) was ready for replacement. The Belzona Membrane System performed so well in its first eight years, the customer naturally chose Belzona again.

APPLICATION SITUATION

Coating on insulated caustic storage tank

APPLICATION METHOD

Once the old coating was removed, the application proceeded in accordance with Belzona® Know-How System Leaflet TCC-4.

BELZONA FACTS

Belzona® 3211 held up well (eight years) in this tough environment. Fumes from neighboring acid tank condensed on a tank, causing rapid deterioration of the previous coatings.

INDUSTRY

Power

LOCATION

Power plant in Texas, USA

APPLICATION DATE

2004

PRODUCTS

Belzona 3211 (Lagseal)
Belzona 3921 (GSC Surface Conditioner)
Belzona 9311 (Reinforcing Membrane Sheet)

SUBSTRATE

Foam insulation over plastic tank

PHOTOS

1. View from acid tank
2. Surface preparation
3. Belzona 3211 applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

