


BELZONA EXPANSION JOINTS REFURBISHED AFTER 5 YEARS SERVICE

ID: 4251



PROBLEM

Over a period of time the exposed surface of the Belzona Elastomer oxidizes allowing it to slowly erode with the water movement.

APPLICATION SITUATION

The original Belzona expansion joints had been in service for 5 years.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-6.

BELZONA FACTS

Belzona Elastomers have a long successful history providing long term repair and maintenance solutions in municipal type swimming pools. The Belzona system is easily maintained to provide long term water containment.

INDUSTRY

Buildings & Structures

LOCATION

Municipal swimming pool, Victoria, British Columbia

APPLICATION DATE

January 2012

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Ceramic tile / Concrete

PHOTOS

1. Some of the Belzona expansion joints after 5 years of service had eroded to below the level of the pool tiles and needed to be "topped up"
2. The old joints were cleaned with a wire wheel to remove all oxidation before being Conditioned
3. Joints refurbished with Belzona 2221

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

