




NON-SLIP SAFETY SYSTEM IN HOSPITAL DISH WASHING ROOM

ID: 436



PROBLEM

Inferior non-slip safety system

APPLICATION SITUATION

Hospital dish washing room floor

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

Customer had contracted with another vendor to apply a non-slip safety system to the dish wash room floor. However, soon after completion of the application, it was found that the surface was extremely slippery. Belzona was approached to apply our standard system over this coating. Within a few months the inferior coating started to delaminate. We were contracted to remove all the red coating and apply a Belzona safety grip system directly to the original floor tiles. Photograph shows removal in progress.

INDUSTRY

General Industry

LOCATION

Regional Hospital - British Columbia, Canada

APPLICATION DATE

1999

PRODUCTS

Belzona 1321 (Ceramic S-Metal)
Belzona 9221 (Surefoot Aggregate)

SUBSTRATE

Quarry tile

PHOTOS

1. Previous failed system being stripped from the floor
2. View of application
3. View of another section of the application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

