


LARGE NON-SLIP SAFETY SYSTEM APPLICATION

ID: 437



PROBLEM

Hospital kitchen and dish washing areas were a constant safety problem because of wet floors. It was determined that the prevention of a single compensation claim would be more than sufficient to justify the cost of the complete application.

APPLICATION SITUATION

Safety system required in hospital kitchen, dishwashing room, and hallway. Total area completed approximately 1,400 square feet.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

During an initial trial period, several safety flooring systems were tested. The Belzona System was voted the best by far by the hospital kitchen and dishroom staff. Three other hospitals and two extended care facilities with Belzona systems (as well as several with competing systems) were consulted. Belzona was awarded the application contract.

INDUSTRY

General Industry

LOCATION

Regional Hospital - British Columbia, Canada.

APPLICATION DATE

February 2001

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Terrazzo floor and light colored quarry tiles.

PHOTOS

1. Preparation underway using a special silicon carbide grinding tool and template
2. Hospital opted for various different 'chevron' style patterns to help break up the areas
3. Another view of application with a different pattern

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.