


NON-SLIP SAFETY SYSTEM SUPERIOR TO SAFETY 'STRIPS'

ID: 438



PROBLEM

Hospital kitchen and dish washing areas were a constant safety problem because of wet floors. Stick on safety strips were in use but had to be replaced on a regular basis. Also loose strips posed an addition problem of tripping.

APPLICATION SITUATION

Slippery quarry tile floor.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

The Belzona system, long term, has been cheaper as it eliminated the constant replacement costs incurred by the 'stick on' safety pads. Contrary to original opinion, cleaning did not pose a problem for the housekeeping staff. Safety was also enhanced as loose or missing strips no longer posed the additional safety problems. This application was extended to other areas.

INDUSTRY

General Industry

LOCATION

Regional Hospital - British Columbia, Canada.

APPLICATION DATE

Various applications starting in 1994

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Quarry tile

PHOTOS

1. Preparation underway using a straight edge template and a saw fitted with a double half inch masonry cutting blade and vacuum. This involved a double pass to achieve the desired 1-inch prepared strip. Masking tape was applied to the edges.
2. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

