

# DISH WASHING ROOM - SAFER WITH BELZONA SYSTEM

ID: 439



## PROBLEM

Hospital dish washing area and store room were a constant safety problem because of wet floors. It was determined that the prevention of a single compensation claim would be more than sufficient to justify the cost of the complete application.

## APPLICATION SITUATION

Safety system required in care centre dishwashing room. Total area completed approximately 700 square feet.

## APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

## BELZONA FACTS

This application came about as a result of the success of other Belzona Non-Slip Safety applications completed within the same organization over the past 10 years. All are still in service with no maintenance required over this time period.

## INDUSTRY

General Industry

## LOCATION

Extended Care Facility - British Columbia, Canada.

## APPLICATION DATE

November 1, 2001

## PRODUCTS

Belzona 1321 (Ceramic S-Metal)

## SUBSTRATE

Light beige seamless epoxy type non-slip flooring material. Despite its surface roughness floor extremely slippery when wet.

## PHOTOS

1. Preparation underway using a special silicon carbide grinding tool and template
2. Hospital opted for various different 'chevron' style patterns to help break up the areas
3. Another view of application with a different pattern

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

