

LEAKY ROOF IS NO PROBLEM FOR BELZONA

ID: 443



PROBLEM

Galvanized roof had numerous leaks around gutters. Previous attempts to stop leaks with conventional roofing materials failed.

APPLICATION SITUATION

Sections of roof gutters

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

BELZONA FACTS

Areas were cleaned, conditioned and two coats of Belzona® 3111 were brushed on. The total area protected with Belzona® 3111 was 8,000 sq. ft.

INDUSTRY

General Industry

LOCATION

Factory roof - Texas U.S.A.

APPLICATION DATE

2001 thru 2004

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3921 (GSC Surface Conditioner)
Belzona 9311 (Reinforcing Membrane Sheets)

SUBSTRATE

Galvanized steel

PHOTOS

1. Conditioned and coated
2. Roof gutters
3. View of roof area
4. Another view of the gutters

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

