

WATERPROOFING CHIME ANGLE WITH BELZONA

ID: 460



PROBLEM

Corrosion was occurring on steel/concrete interface of wastewater tank and pad.

APPLICATION SITUATION

Tank Chime Angle

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-3.

BELZONA FACTS

Customer had used Belzona® 3111 on many other water proofing repairs. Numerous attempts using caulking materials did not stand up to the requirements.

INDUSTRY

Power

LOCATION

Power Plant - Texas USA

APPLICATION DATE

May 2004

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3921 (PSC Surface Conditioner)
Belzona 9311 (Membrane Reinforcing Sheet)

SUBSTRATE

Steel and concrete

PHOTOS

1. Close look at the problem area
2. Prepared surface taped off
3. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.