

BELZONA SEALS LEAKING MUSIC ROOM ROOF

ID: 4630



PROBLEM

Breakdown of the old bituminous substrate had allowed multiple areas of water ingress causing damage to the fabric of the building & creating health and safety issues. Due to its location adjoining a listed school building a hot applied system was not acceptable.

APPLICATION SITUATION

Roof over the music room at a prestigious private school

APPLICATION METHOD

The application was carried out in strict accordance with Belzona System leaflet RPA-1.

BELZONA FACTS

The Belzona solution being cold curing, combined with its ease of application and ability to seal the various roof details met the clients requirements.

INDUSTRY

Buildings & Structures

LOCATION

Prestigious boarding school, Somerset, England

APPLICATION DATE

August, 2012

PRODUCTS

Belzona 3131 (WG Membrane)

SUBSTRATE

Bitumen

PHOTOS

1. Close up of previous repairs which had failed
2. Preparation of the roof by removing loose chippings
3. First coat of Belzona 3131 being applied with reinforcement sheet
4. Completed application several months later

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

