

KITCHEN SAFETY IMPROVED THANKS TO BELZONA

ID: 465



PROBLEM

Routine health inspection had highlighted hygiene and safety problems with the floor area necessitating refurbishment before the school re-opened.

APPLICATION SITUATION

Floors in kitchen area

APPLICATION METHOD

Two coats of Belzona® 5231 were applied after thoroughly cleaning and grit blasting the existing tiled surface.

BELZONA FACTS

Belzona® 5231 created a hygienic, seamless floor surface with the right degree of non-slip to provide safe footing for the kitchen staff. The application was completed smoothly in the short holiday period during which the school was closed.

INDUSTRY

General Industry

LOCATION

School in UK

APPLICATION DATE

July 2002

PRODUCTS

Belzona 5231 (SG Laminate)

SUBSTRATE

Quarry tiles

PHOTOS

1. Kitchen area prior to the Belzona application
2. Wash area prior to the Belzona application
3. Belzona 5231 applied
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.