

INSPECTION PIT SAFETY IMPROVED WITH BELZONA

ID: 466



PROBLEM

Routine refurbishment of the workshops was being undertaken with particular emphasis on improving safety in and around the inspection pits.

APPLICATION SITUATION

Workshop floors including inspection pit

APPLICATION METHOD

After scabbling the concrete and planing rough areas a two-coat system of Belzona® 5231 was applied to the workshop floor and inspection pit. An additional strip of Belzona® 4411 grip system was applied to step nosings to provide additional grip and safety.

BELZONA FACTS

A total of seven workshops have now been refurbished. The applications only took place after testing of the system to ensure it was capable of performing well in the arduous workshop conditions where a variety of military vehicles up to four ton trucks are serviced.

INDUSTRY

General Industry

LOCATION

Military installation - UK

APPLICATION DATE

July 2002

PRODUCTS

Belzona 5231 (SG Laminate)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. Overview of the inspection pit, following application.
2. Belzona systems improve safety on steps too.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

