




BALCONIES WATERPROOFED WITH BELZONA

ID: 4691



PROBLEM

The aging balconies had numerous fine cracks and the hotel had been suffering from water penetration issues. With high occupancy rates a quick turnaround was essential.

APPLICATION SITUATION

Balconies on Victorian era hotel

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-15. the Belzona 5811 was applied using brushes and squeegees.

BELZONA FACTS

Due to the products solvent free properties the contractor was able to complete the application very quickly and without any disruption to the hotel guests. The standard grey colour also complemented the existing colour scheme on the exterior of the hotel. As the balconies don't get used there was no need for a grip system.

INDUSTRY

Buildings & Structures

LOCATION

Boutique Hotel, London

APPLICATION DATE

June 2013

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Unprotected balconies
2. Contractor carrying out application
3. & 4. Completed work

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

