

QUICK AND EASY DOOR REPAIR WITH BELZONA

ID: 4692



PROBLEM

A new door had been fitted with a new lock and catch. The position of these had to be changed leaving two cut outs in the door frame from the old lock and separate catch.

APPLICATION SITUATION

Damaged door frame

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-5. A Belzona plastic applicator was used both to apply the product and as a former to create the required profile.

BELZONA FACTS

The repair was carried out in less than one hour from start to finish and in one site visit. The alternative repair for the Housing Association had been replacing door frames. Far more costly and time consuming.

INDUSTRY

Buildings & Structures

LOCATION

Housing Association, Worcester, UK

APPLICATION DATE

September 2013

PRODUCTS

Belzona 8111 (Mouldable Wood)

SUBSTRATE

Wood

PHOTOS

1. Damaged door frame
2. Applying Belzona 8111
3. Completed wood repair
4. Painted finish

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

