

BELZONA ALLOWS HOUSTON CLARIFIER TO BE CLEAR AGAIN

ID: 4701



PROBLEM

With damaged concrete and no coating, the trough was hard to keep clean, taking 2-3 times longer than when new.

APPLICATION SITUATION

The customer was looking for a long-term repair in lieu of repairing it every 2-3 years as they have done in the past. With experience in other areas of the facility, the customer felt confident Belzona could do just that.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-9.

BELZONA FACTS

The Belzona repair was able to be carried out over a long weekend at the facility in comparison to the competition taking them down for over a week, Belzona was chosen not only for the quick turn-around but also for a proven track record at the facility on other repairs. The facility saved time and money.

INDUSTRY

Water / Wastewater

LOCATION

Houston, TX, USA

APPLICATION DATE

September 2013

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Overall view of clarifier
2. After rebuilding with Belzona 4131
3. Completed project
4. Completion application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

