

COOLING WATER PIPE REBUILT AND PROTECTED WITH BELZONA

ID: 4706



PROBLEM

The customer had a short outage where the cooling pipes had to be repaired or replaced. Repairing with Belzona gave the customer a quick turnaround and was much more economical.

APPLICATION SITUATION

Splash and spill from the nearby cooling tower caused severe pitting on the top portion of the cooling water pipes. Pipes were so thin that leaks were springing up weekly.

APPLICATION METHOD

The application was carried out with a modified version of Belzona Know-How System Leaflet VPF-1.

BELZONA FACTS

Belzona had the repairs done in days, whereas replacement would have taken weeks, with a much more economical solution and a long lasting repair.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

Orange, TX

APPLICATION DATE

March 2013

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 5811 (Immersion Grade)
Belzona 5111 (Ceramic Cladding)

SUBSTRATE

Carbon Steel

PHOTOS

1. Before application.
2. Through-holes and pitting filled.
3. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

