

BELZONA PROTECTS WALLS AND FLOORS AT CIDER PLANT

ID: 4707



PROBLEM

The area was un-hygenic and also needed brightening up with materials that were easy to clean. The floor also needed a safe non-slip surface.

APPLICATION SITUATION

A very damp and dirty pit area.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets WPA-2, FPA-1 and FPA-8. The damaged areas of the floor were rebuilt using the Belzona® 4131 before coating with Belzona® 5231. Belzona® 5111 system was applied to the walls.

BELZONA FACTS

Belzona was chosen for this project due to its proven success on site over many years. In particular the easy clean properties of Belzona® 5111 enable high levels of hygiene to be maintained.

INDUSTRY

Food & Drink

LOCATION

Cider producer, Herefordshire, UK

APPLICATION DATE

December 2012

PRODUCTS

Belzona 5111 (Ceramic Cladding)
Belzona 5231 (SG Laminate)
Belzona 4131 (Magma Screed)

SUBSTRATE

Block Wall and Concrete Floor.

PHOTOS

1. View into pit before application
2. pit after application
3. walls before application
4. walls after application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

