

BELZONA GIVES OLD PROPERTY NEW LEASE OF LIFE

ID: 4708



PROBLEM

Failure of the existing paint was allowing damp to penetrate into the walls leading to further deterioration. Client needed system to protect walls and approve appearance.

APPLICATION SITUATION

Old farm house walls.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-1. A mechanical wire brush was used over the entire surface to remove loose material. After treating with fungicidal wash the Belzona® 5151 system was applied.

BELZONA FACTS

Due to the contractor using Belzona products on a number of very successful applications within the social housing sector they were able to demonstrate the effectiveness of the Belzona® 5151 system to the client.

INDUSTRY

Buildings & Structures

LOCATION

Farm house, Worcestershire, UK

APPLICATION DATE

June 2013

PRODUCTS

Belzona 5151 (High Build Cladding)

SUBSTRATE

Brick

PHOTOS

1. Surface Preparation
2. Application of Belzona 3911 (PSC Conditioner)
3. Completed Belzona 5151 Application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

