

BELZONA REPAIRS PST AT WATER TREATMENT PLANT

ID: 4711



PROBLEM

Walls of the running track had become badly worn and damaged over time due to rotation of the distributor. Some areas had been unsuccessfully repaired in the past.

APPLICATION SITUATION

Concrete wall of a Primary Settlement Tank (PST)

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 & FPA-6. Once the surface was prepared, shuttering boards were fitted to the side walls to enable the Belzona® 4131 to be applied to accurate levels. Once the Belzona 4131 had cured the boards were removed and expansion joints cut into the repaired areas. These joints were then sealed with Belzona® 2211.

BELZONA FACTS

The Belzona solution was chosen due to the quick turnaround compared to other methods. Also the failure of the previous patch repairs led them to the need for a permanent repair. The longevity of the Belzona solution backed up by case histories supported the proposal.

INDUSTRY

Water / Wastewater

LOCATION

Water treatment plant, Gloucestershire, UK

APPLICATION DATE

October 2012

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Concrete

PHOTOS

1. Damaged running track and failed previous repairs
2. Shuttering boards being installed
3. Completed repair back in service
4. Repaired areas 12 months on

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

