


BELZONA EXTENDS LIFE OF CYCLONE CONES IN QUARRY WASH PLANT

ID: 4713



PROBLEM

The cones suffer heavy levels of abrasion. The mean times between failures of the cones was not acceptable even after the rubber coating was applied and continuing stoppages of the plant had large cost implications. Belzona was selected for a trial application to increase the working life of these components.

APPLICATION SITUATION

Cones on cyclone wash plant filtration. Non-protected cones were failing within one month and rubber coated cones only lasted for six months.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-13.

BELZONA FACTS

Original cones with no coating last 1 month. Rubber lined cone lasts 6 months cost per cone £150 Belzona solution lasted 18 months. Cost per cone £200 The largest cost saving was on down time to the wash plant. After the successful trial the client has now made the Belzona solution the standard for all the abrasion areas within this plant.

INDUSTRY

Mining & Quarrying

LOCATION

Lime stone quarry, SW, England

APPLICATION DATE

February 2012

PRODUCTS

Belzona 1812 (Ceramic Carbide FP)

SUBSTRATE

Steel

PHOTOS

1. Cone prior to application
2. Clients staff carrying out application
3. Belzona 1812 during application
4. Completed application of Belzona 1812 to cone

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

