

BELZONA SEALS LARGE BUND AREA

ID: 4714



PROBLEM

The site is very keen on keeping up there high standards in health and safety and environmental issues and so regularly test for leaks .The bund was leaking in many areas through the brickwork.

APPLICATION SITUATION

Chemical Bund on large manufacturing site

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets TCC-9 and TCC-15. The application took place during the planned two week shutdown and so no disruption to production.

BELZONA FACTS

Belzona has been used on this site to provide solutions in a number of different areas. They now look to Belzona as "Problem Solving" and look to us to come up with alternative solutions to traditional repairs.

INDUSTRY

Steel & Metal Processing

LOCATION

Metals manufacturer, Herefordshire, UK

APPLICATION DATE

November 2012

PRODUCTS

Belzona 5811 (Immersion Grade) Belzona 4131 (Magma Screed)

SUBSTRATE

Brick

PHOTOS

1. Before application
2. Creation of fillets at wall/floor joint with Belzona 4131
3. Application of first coat Belzona 5811
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

