

BELZONA SOLVES FINLOCK GUTTER ISSUES

ID: 4715



PROBLEM

Finlock gutters had begun to leak into the properties.

APPLICATION SITUATION

Rows of Finlock Gutters on Housing Association Properties.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-6 and RPA-11. Any damaged areas of concrete were repaired using Belzona 4141 followed by complete coating with the reinforced Belzona 3131 system.

BELZONA FACTS

The housing association had tried a number of different solutions including metal liners, felt and another liquid applied product. Belzona has a long successful history of repairing and sealing finlock gutters.

INDUSTRY

Buildings & Structures

LOCATION

Housing Association, Herefordshire, UK

APPLICATION DATE

March 2013

PRODUCTS

Belzona 3131 (WG Membrane) Belzona 4141 (Magma Build)

SUBSTRATE

Concrete

PHOTOS

1. Before Application 2. Removal of existing liners 3. Application in progress 4. Completed Application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

