

BELZONA FENDER REPAIR

ID: 4718



PROBLEM

Fenders on these boats were getting damaged which in turn increased likelihood of damage during contact with other ships. Replacement during annual docking was costly and replacement at other times interrupted busy schedules.

APPLICATION SITUATION

Fenders on tug boats operated by a major marine services company. these boats guide ships in and out of the Worlds ports, providing safe access into the ports and shipping lanes.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

The Belzona repair solution worked out to be a quarter of the replacement cost, Also the repair didn't cost the company any down time as it was carried out between shifts. The repairs were carried out by the crew of the Tug at the quay side. Within hours the Tug was back in service and operating in a safe manner.

INDUSTRY

Marine

LOCATION

Port, South East England

APPLICATION DATE

July 2013

PRODUCTS

Belzona 2211 (MP Hi Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Tug pulled up ready for a fender repair
2. Damaged fender before repair
3. Fender being prepared for the rebuild
4. Completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

