

BELZONA UPGRADES DAMAGED WALLS IN PROCESS AREA

ID: 4726



PROBLEM

Due to chemical spills and damp conditions the walls were in need of repair and protection.

APPLICATION SITUATION

Damaged walls in process area.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet WPA-2 and WPA-4. The damaged areas of the wall were rebuilt using the Belzona 4131. Belzona 5111 system was then applied to the upper areas and Belzona 5231 to the lower areas to give the aesthetic finish required.

BELZONA FACTS

Years of successful applications on site and being able to provide the colour they required were important factors in their decision to go with Belzona.

INDUSTRY

Food & Drink

LOCATION

Beverage producer, Herefordshire, UK

APPLICATION DATE

September 2013

PRODUCTS

Belzona 5111 (Ceramic Cladding) Belzona 5231 (SG Laminate) Belzona 4131 (Magma Screed)

SUBSTRATE

Block Walls

PHOTOS

1. Damaged wall area 2. Belzona 5111 application 3. Belzona 5231 applied 4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

