

BELZONA SEALS CANOPY ROOF

ID: 4739



PROBLEM

Asphalt roof covered with solar reflective paint had deteriorated due to coastal winds, sea spray and uv light over a number of years. The roof was now leaking. Customer needed roof to be fully waterproof especially as this was to be part of a new bus station.

APPLICATION SITUATION

Old canopy roof which was to form part of a new bus station.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet RPA-6. A simple pull-off test was done to determine which conditioner was best for the weathered solar reflective paint. This proved to be Belzona 3911 (PSC Conditioner). Roof was power washed and Belzona 3911 applied. Two coats of Belzona 3111 were applied with Reinforcing sheet. The result was fully sealed waterproof roof with a seamless finish.

BELZONA FACTS

Belzona was preferred due to BBA certification, it being low odour and being flexible along with ease of application for customer's own contractor. Support was provided to contractor throughout the application, a requirement of the customer to ensure application was completed within the timescale provided.

INDUSTRY

Buildings & Structures

LOCATION

Bus Station, Lancashire, UK

APPLICATION DATE

Sept 2012

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Asphalt

PHOTOS

1 & 2 General views of the roof before work commenced

3 & 4 Completed roof showing seamless finish achieved

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

