


BELZONA REFURBISHMENT OF FLAT ROOF

ID: 4742



PROBLEM

The felt roof had deteriorated allowing numerous leaks into the areas below.

APPLICATION SITUATION

Large areas of flat roof over the sports and dining areas.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets RPA-1, RPA-6 and RPA-8. After cleaning the roof and carrying out some localised repairs, a fully reinforced Belzona 3111 system was applied to the entire roof areas.

BELZONA FACTS

Client had already used Belzona on various roofing projects in the past and was happy with the system. The use of Belzona allows the roofs to be upgraded with minimal disruption.

INDUSTRY

LOCATION

School, Grantham, UK

APPLICATION DATE

2013

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Felt

PHOTOS

1. Section of roof before work started
2. Completed application
3. Upper section of roof before coating
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

