

BELZONA PREVENTS LEAKS INTO ELECTRICAL ROOM

ID: 4786



PROBLEM

The leak was over the hotel electrical room causing periodic power disruptions.

APPLICATION SITUATION

A leak had developed between the brick wall and the parking garage floor.

APPLICATION METHOD

Application was carried out using a modified version of Belzona System Leaflet RPA-1. The area along the wall and concrete floor was ground with a Vac-grinder to ensure a good surface for bonding before applying the Belzona 3121 system.

BELZONA FACTS

This use of Belzona 3121 allowed for a quick turn around and minimal disruption to the hotel vehicle traffic in the area.

INDUSTRY

Buildings & Structures

LOCATION

Hotel Chain, Vancouver, BC, Canada

APPLICATION DATE

October 2009

PRODUCTS

Belzona 3121 (MR7 Membrane)

SUBSTRATE

Brick and Concrete

PHOTOS

1. Surface preparation underway 2. The area was masked off before the 1st coat of Belzona 3121 was applied 3. A 2nd coat of Belzona 3121 was applied along with reinforcing sheet to ensure that the gap was adequately bridged. A 3rd coat was applied to complete the application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

