

BELZONA STOPS DAMAGE FROM PITTED CHOCKS

ID: 48



PROBLEM

Chocks pitting and the roughness was destroying the hawsers.

APPLICATION SITUATION

Pitted chocks

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How Leaflet SOS-19.

BELZONA FACTS

Ship's mooring lines (hawsers) are very expensive. The steel casting for the chocks became pitted from the salt. This caused jagged edges which wore out the hawsers prematurely.

INDUSTRY

Marine

LOCATION

Oil tanker, Pacific Northwest, U.S.A.

APPLICATION DATE

1998

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

SUBSTRATE

Steel

PHOTOS

1. Close-up of chock with peeling paint.
2. View of chock showing extensive pitting.
3. Surface preparation in progress.
4. Finished application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

