

BELZONA 4111 (MAGMA-QUARTZ) KEEPS PRODUCTION ON TRACK

ID: 481



PROBLEM

Fork lift traffic damaged stainless steel plate being bent by fork lift trucks pushing pallets into it and lifting it up. Needed a solution to avoid further damage.

APPLICATION SITUATION

Loading dock - stainless steel plate

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and FPA-10.

BELZONA FACTS

Very little time to consider alternatives, which would have been costly as the facility operates 24/7. Also, a government inspection was on the near horizon, and this problem could have caused the facility to fail an inspection. The use of Belzona® 4111 (Magma-Quartz) allowed the facility to quickly and very cost effectively keep production on track.

INDUSTRY

General Industry

LOCATION

Animal food manufacturer - Missouri USA

APPLICATION DATE

November 2004

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete & stainless steel

PHOTOS

1. Close up of the problem
2. Surface prepped
3. Ready for traffic

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.