

SUCCESSFUL RESTORATION OF ROOF IN CENTRAL LONDON WITH BELZONA

ID: 4824



PROBLEM

Despite the roof appearing to be in good condition, it was found to be leaking in several places. This had become a business critical situation as there was a plant room containing sensitive electrical equipment located directly below the leaks. It was therefore of the utmost importance that the roof was repaired quickly and efficiently.

APPLICATION SITUATION

Inverted roof covered in a single-ply membrane.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1. The upper level roof was cleaned and prepared before application of a fully reinforced Belzona 3111 system.

BELZONA FACTS

Following a successful roofing application two years earlier, Belzona were approached again by the company to repair and protect the leaking roof. The Project Co-ordinator said, "The contractors who carried out the works did a great job in a professional manner and we experienced no interruptions to business or complaints throughout the entire project. I will definitely be recommending Belzona in any future projects where their system can be used."

INDUSTRY

Commercial Facilities

LOCATION

Finance company, central London

APPLICATION DATE

August 2012

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Single-ply membrane

PHOTOS

Surface being conditioned to ensure good adhesion
First coat of Belzona 3111 applied
Completed application
Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

