

BELZONA RINGS A TUNE

ID: 484



PROBLEM

Roof leaks

APPLICATION SITUATION

161-foot bell tower

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8.

BELZONA FACTS

The roof area is approximately 30 square feet with a hatch opening. Customer had been advised that the roof should be removed to be repaired. Belzona® 3111 was used to repair the roof in place, saving significant amounts of money.

INDUSTRY

Buildings & Structures

LOCATION

University in Southern California, USA

APPLICATION DATE

August 2004

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete

PHOTOS

1. The bell tower
2. Leaks were allowing water to ingress the bells bellow
3. Problems clearly evident
4. Completed roof repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

