


VULCANIZING COMPANY SAVES TIME AND MONEY

ID: 4870



PROBLEM

The tire had a cut which penetrated right through the wall, requiring repairs to be performed not only on the outside but on the inside of the tire as well.

APPLICATION SITUATION

Off-road tractor's tire

APPLICATION METHOD

The affected areas (both inside and outside of the tire) were abraded then fully cleaned and degreased. Then, the substrate was conditioned using Belzona 2911 (Elastomer QD Conditioner). Belzona 2311 (SR Elastomer) was then mixed and applied incorporating Belzona 9341 (Reinforcing Tape) to the area around the damage.

BELZONA FACTS

The tire was returned to service and is performing as good as new. This Belzona repair was quick and easy to complete, saving time and money to the end client.

INDUSTRY

Mining & Quarrying

LOCATION

Vulcanizing Company, Southwest Scotland.

APPLICATION DATE

January 1996

PRODUCTS

Belzona 2311 (SR Elastomer)
Belzona 2911 (Elastomer QD Conditioner)
Belzona 9341 (Reinforcing Tape)

SUBSTRATE

Rubber

PHOTOS

1. Inside portion of the tire before the repair
2. Surface preparation in progress
3. Inside repair near completion
4. Finished repair to the outside

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

