

BELZONA ENSURES TIGHT FIT OF DRAGLINE BUCKET TEETH

ID: 4882



PROBLEM

The loss of bucket teeth in the coal pit causes severe problems when they are discovered in the crushers, causing major damage to downstream equipment.

APPLICATION SITUATION

Bucket teeth shimming

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS -9.

BELZONA FACTS

Using Belzona 1111 as a shim when replacing the teeth allowed for a tight fit and was easily repaired with minimal downtime.

INDUSTRY

Mining & Quarrying

LOCATION

Mining Industry, USA

APPLICATION DATE

June 1999

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Dragline bucket overview
2. Application of Belzona 1111
3. Complete application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

