

LEAKY ROOF REPAIRED WITH BELZONA DODGING A THUNDERSTORM

ID: 4885



PROBLEM

The warehouse roof leaked for over 20 years with 5 different contractors trying to fix it.

APPLICATION SITUATION

Roof leak

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

BELZONA FACTS

Belzona 3111 was used, dodging a thunderstorm in 3 weeks. It has not leaked a drop in 8 years now.

INDUSTRY

LOCATION

Coal Mine, USA

APPLICATION DATE

May 2006

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Steel

PHOTOS

1. Problem area
2. Application in progress
3. Complete application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

