

BELZONA REPAIRS SWING SHAFT BUSHING

ID: 4886



PROBLEM

Swing shaft bushing are segmented brass and fit loosely. Belzona was used to shim the OEM bushings for a tighter fit.

APPLICATION SITUATION

Damaged swing shaft bushing on a dragline

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-7. Surface was cleaned and degreased from oils and prepared using hand tools.

BELZONA FACTS

Bushings were replaced often due to the loose fit. Belzona 1111 repair augmented the OEM fit thus improving run life.

INDUSTRY

Mining & Quarrying

LOCATION

Mining Industry, USA

APPLICATION DATE

October 2009

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Damaged bushing
2. Application in progress
3. Complete application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

