

BELZONA SAFETY GRIP SYSTEM FOR ROOF ACCESS STAIRS

ID: 4887



PROBLEM

Extensive water and salt exposure had made it virtually impossible to maintain the Health and Safety requirements for any extended period of time.

APPLICATION SITUATION

Access to the roof via the smooth stairs.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Removed the existing adhesive tape and prepared the area ready for application. Belzona 4411 with Belzona 9211 was applied to eighteen steps and nosings.

BELZONA FACTS

The client was looking for a quick solution to be able to comply with Health and Safety requirements and selected Belzona as not only did it offer a quick repair but also provided a long-term solution. The application was completed within 5 hours and the client was able to reuse the stairs the next day.

INDUSTRY

LOCATION

Markham, Ontario, Canada

APPLICATION DATE

December 2013

PRODUCTS

Belzona 4411 (Granogrip)
Belzona 9211 (Super Grip Aggregate)

SUBSTRATE

Terrazzo flooring

PHOTOS

1. Stairs prior to application
2. Preparation complete
3. Application in progress
4. Complete application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

