

CORROSION PROTECTION FOR ROLLERCOASTER

ID: 4920



PROBLEM

Uncoated and unprotected carbon steel structural anchor bolts exposed to outdoor elements causing Corrosion at a large theme Park attraction.

APPLICATION SITUATION

Approximately 1700 Structural anchor bolts at the base of a roller coaster.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-2. The surface was prepared by removing any contamination by rotary wire wheel and then cleaned with Belzona 9111. Two coats of the Belzona 5831 were applied with a brush to the anchor bolts in accordance with the Belzona Instructions For Use.

BELZONA FACTS

Belzona 5831 is an environmental moisture tolerant barrier coating and does not corrode. The Belzona 5831 protects the steel underneath the coating and stops the steel from further corrosion.

INDUSTRY

Buildings & Structures

LOCATION

Vaughan, Ontario, Canada

APPLICATION DATE

October 2013

PRODUCTS

Belzona 5831 (ST-Barrier)

Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Carbon Steel

PHOTOS

1. Anchor bolts prior to application
2. Application underway
3. View of an anchor bolt finished application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA