

BELZONA PROTECTS NEW CHILLER

ID: 4925



PROBLEM

Due to the operational environment of the plant the Chiller was expected to suffer constant corrosion during operation if not protected. Based on their previous experience the customer decided to pro-actively prevent future damage by specifying Belzona be applied to the new unit.

APPLICATION SITUATION

Chemical plant buying new chiller specified Belzona coating to protect their investment.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflets HEX-1 & HEX-3

BELZONA FACTS

The chemical plant used to suffer from constant problems and shutdowns on similar chiller units. In 2009 Belzona solution was applied on 5 old chiller units and since then followed by yearly inspection the units are in perfect condition. Based on their previous experience the customer decided to prevent damage to the new unit by protecting with Belzona.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chiller Manufacturing Facility, Israel

APPLICATION DATE

2013

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Tube sheet before application
2. Corking of the tube sheet
3. Tube sheet coated with Belzona 1321
4. Completed coated tube sheet

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®