

GARBAGE ROOM FLOOR REPAIR AND COATING AT A MALL

ID: 4936



PROBLEM

A combination of waste causing chemical attack and physical damage caused by large roll on, roll off containers.

APPLICATION SITUATION

Garbage room floors.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. The surface was prepared by removing any existing coating and loose material or contamination and abraded to expose the aggregate. Belzona 4131 was applied to rebuild and repair the damaged concrete. Belzona 5231 was applied to the garbage room floor with a roller in accordance with Belzona Instructions For Use.

BELZONA FACTS

The repairs and coating provide resistance to the daily activities, wear and attack. Eighteen months after application (March 2014) the system is performing excellent.

INDUSTRY

Buildings & Structures

LOCATION

Burlington, Ontario, Canada

APPLICATION DATE

August 2012

PRODUCTS

Belzona 4131 (Magma-Screed) Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1.Flooring prior to application
2.Application in progress 3.Complete application 4.Eighteen months after application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

